

FIG. 1

Prior art





Figure 2 Prior art



**Figure 3 (prior art)**

# Borehole Size Correction for an HDLL lateral subarray K = 53.883; Tool Centered







Figure 4 (prior art)



**Figure 5a (prior art)**



**Figure 5b**



**Figure 6**




Figure 7